



REQUEST FOR QUOTATION: FIRE COMPLIANCE ASSESSMENT

Kindly see the attached request for quote (RFQ). Quotations should be forwarded to weziwe@bccollege.co.za; cc: zimkhitha@bccollege.co.za

Kindly submit the following COMPULSORY documents when responding to the RFQ

- Signed quotation (quotations not signed will be eliminated)
- Declaration forms (SBD 4, 8 and 9)
- Certified BEE certificate (0 points will be awarded for BEE certificates that are not certified)
- Tax Clearance Certificate
- CSD report
- Bank Confirmation Letter (not older than 3 months)

Closing Date: 08 November 2021 at 11h00am. No late or hand delivered documents will be accepted. ONLY EMAILED DOCUMENTS WILL BE ACCEPTED

Enquiries: Ms Weziwe Gwabavu / Zimkhitha Jikwana 043 704 9241





ROUTE FORM

	Confidential x Secr	et	
SUBJECT: FIRE COMPLIA	ANCE CERTIFICATE FOR THE COLLEGE		Top secret
Branch: Academic Services	Directorate: Assessments and Examinations	Sub-c	directorate:
nitials and Surname	Compiler		
ank	P MAWILA		
ate	DP: ACADEMIC SERVICES 28 SEPTEMBER 2021		
ktension	2214 2214		
oom number	AD15		
Route			

	Route						 _	
Designation DP: Academic Services	Initial & Surname	Room	+		То		Return	date.
	, mavila	no. AD15	×	Initial PM	Date 28-09-202()		Date	No.
DP: Corporate Services	Z Chola	AD 09	X		20-09-2020	X		
cting DP: Finance	L Maliwa	AD 12	X	S.C.	28/09/2021			
cting PRINCIPAL	P Madzeke	AD 01	X		,	X		
			^		3	-		

Indicate route with an "X". The return route must already be indicated at the time of dispatch.

Instructions/ Comments	dicated at the time of dispatch.





ACADEMIC SERVICES

TO: P Madzeke Acting Principal: Buffalo City TVET College CC: Z Chola DP: Corporate Services L Maliwa Acting DP: Finance	FROM: P Mawila DP: Academic Services DATE: 28 /09 /2021
SUBJECT: FIRE COMPLIANCE CERTIFICATE FO	OR THE COLLEGE

1. Purpose

This letter serves to seek approval for the appointment of a service provider to perform fire compliance assessment and manage the process of issuing fire compliance certificate by the municipality.

2. Background

During each examination cycle the college campuses are found not compliance with fire certificate including 24 hour alarm system which linked to the security company. The examination monitoring tool has been used to measure the college outcome items of the management of examinations as outlined in the strategic plan document.

3. Recommendation

I therefore recommends that the appointment of a service provider before the start of the coming examination cycle as from 28 October 2021 – 03 December 2021.

4. Conclusion:

I trust that you will consider this proposal and approve it as soon as possible.

DP: Academic Services Date: 2809 200
Recommendations: Supported Not Supported Z Chola DP: Corporate Services Date: 28109 1287 Comments:
Recommendations: Supported/Not Supported
L. Maliwa Acting DP; Finance Date: 3509 250 Comments:
Recommendations: Not Approved/ Approved/ Amended
Madzeke
Acting Principal: Buffalo City TVET College Date:
Date: Comments: King Street Canpus unliked BCMM to de perform teer freter so let's unlike terr Serma.
Serma.





Occupation health and safety proposed specification East London Campus and Admin Centre

1. Emergency alarm system that can be used to inform the occupants in the event of an 2. Exit signage is required for the passage.

- 3. A running man and arrow to show the direction to be travelled by occupants in case of an emergency is required at admin centre and staff room.
- 4. A distance of one metre clearance is required to all fire equipment.

5. Exit signage is required from the hall door

6. Flammable storage is required to have a permit.

7. All computer laboratories must have smoke detectors.

8. All signage must meet SANS 1186 approved, photolumicent and must be screwed

John Knox Bokwe Campus:

- 1. Emergency alarm system that can be used to inform the occupants in the event of
- 2. All fire extinguishers are required to be serviced yearly.
- 3. Store room stack should be 1 metre from the roof.
- 4. One metre clearance is required to all fire equipment.
- 5. Exit signage is required for the central garden
- 6. All flammable storages are required to have bund wall.
- 7. The book storeroom is required to have three extinguishers with a signage.
- 8. All hydrants require servicing and a pressure test by your service provider must be
- 9. All computer laboratories are required to have smoke detectors.
- 10. All doors that is a component of an escape route any room require a running man
- 11. All doors in an escape route at the ground level, leads directly to a street or public place or to any approved open space require exit signage.

12. The hall require fire hose reel with a signage.

- 13. At data capture section all obstructions must be removed in the route of emergency
- 14. All signage must meet SANS 1186 approved, photolumicent and must be screwed

ST Marks Campus

- 1. Emergency alarm system that can be used to inform the occupants in the event of
- 2. All fire extinguishers are required to be serviced yearly.
- 3. Store room stack should be 1 metre from the roof.
- 4. One metre clearance is required to all fire equipment.
- 5. Exit signage is required at Mr Zihlwele
- 6. A fire extinguisher is required for each office and a person must not travel mountain 6
- 7. All doors that is a component of an escape route from any room require running man
- 8. All doors in an escape route at the ground level, leads directly to a street or public place or to any approved open space requires

- 9. All obstructions must be removed in an emergency.
- 10. Assembly points must be marked clearly.
- 11. Bursary office require 2 extinguishers with a signage.
- 12. All vendors must have environmental health certificate.
- 13. All signage must meet SANS 1186 approved, photolumicent and must be screwed into the wall.

King Street Campus

- 1. Emergency alarm system that can be used to inform the occupants in the event of any emergency is required
- 2. All fire extinguishers are required to be serviced yearly.
- 3. One metre clearance is required to all equipment.
- 4. A fire extinguisher is required for each office and the person must not travel more than 6 metres long to reach the fire equipment.
- 5. All passages must have smoke detectors.
- 6. Evacuation plan is required.
- 7. Staircase signage is required.
- 8. All doors that is a component of an escape route from any room required running man signage with an arrow.
- 9. All doors in an escape route at the ground level, lead directly to a street or public place or to any approved open space require exit signage.
- 10. All obstructions must be removed in an emergency route.
- 11. All signage must meet SANS 1186 approved, photolumicent and screwed into the wall.

All campuses must have emergency assembly point including marked demarcated smoking areas

Buffalo City Metropolitan Municipality East London | Bhrahe , King William's Town Province of the Eastern Code South Africa

Wabsite: now ouffeloo ty gov 24



& Emergency Services Office of the Chief Fire Officer P. O Box 673, East London, 5200 47 Fleet Street, East London 5201

Directorate: Health, Public Safety

Tel: 043 7059007 | Fax: 043 742 0092 Email: ZolekaM@buffalocity.gov.za

Our ref.: Ifavile yethu: 17, 10 1/3

Mrs N. Nanto Imibuzo: Ext. 9007

Your ref.: Ifayile yakho:

Navrae:

Eng.:

U Verw.:

09 MARCH 2018

Ons Verw.:

The Manager **Buffalo City TVET College** Corner Lukin Road & Kings Street **EAST LONDON** 5200

Dear Sir/Madam

FIRE SAFETY INSPECTION LETTER FOR EAST LONDON CAMPUS AND ADMIN RE: CENTRE

The Buffalo City Metropolitan Municipality Fire and Rescue Services conducted a fire safety inspection at above mentioned campus on the 15th January 2018.

1 FINDINGS

- No emergency alarm system in place.
- No fire early warning device installed in the building.
- No sufficient running man signs and arrow to show the direction to be travelled by occupants in case of an emergency.

AND THE FOLLOWING NEED TO BE DONE:

- Emergency alarm system that can be used to inform the occupants in the event of an emergency is required.
- Exit signage is required for the passage.
- A running man sign and arrow to show the direction to be travelled by occupants in case of an emergency is required at Admin Centre and Staff Room.
- Store room stack should be 1 metre from the roof.
- A distance of one metre clearance is required to all fire equipment.
- Exit signage is required for the hall door.
- Flammable storage is required to have a permit.
- All Computer Laboratories must have smoke detectors.
 - All signage must meet SANS 1186 Approved, photolumicent and must b screwed into the wall.

BUFFALOCITYMETROPOLITANMUNICIPALITY





If you have any further queries regarding the above, please contact Mrs N. Nanto on [043] 705 9007

T. THÓMPSON

CHIEF FIRE OFFICER

DATE: 22 NOVEMBER 2017

EMPLOYEE NUMBER:

592914

AUTHORITY NUMBER:

3/2



BUFFALO CITY METROPOLITAN MUNICIPALITY

OFFICE OF THE CHIEF FIRE OFFICER BUFFALO CITY FIRE AND RESCUE DEPARTMENT

APPLICATION FOR CERTIFICATE

	<u>RENEWABLE ANNUALY</u>
Fire Compliance	Population
Certificate	Certificate
COST PER CERTIFICATE 0- 250	0sq/m = R250 00. 251 - 700sq/m = R500.00
701 1000so/m = R750 00, ab	ove 1000 sq/m = R1 122.00
ADIETED AND EQUALD	OED TO THE CHIEF FINANCIAL
	FOLLOWING FEES: 1800sq/m R750 00 above 1000sq/m =
	COST PER CERTIFICATE 0-250 701 100086/10 = R750 00, ab

Please make payment at Municipal offices at Finance in Munifin Building, Oxford Street or electronic transfer payable to:

CREDITOR: BUFFALO CITY METROPOLITAN MUNICIPALITY BANK NAME: STANDARD BANK

TYPE OF ACC: BUSINESS CURRENT ACCOUNT

ACCOUNT NO: 081166702 BRANCH CODE: 051001

Buffalo City Metropolitan Municipality East London | Bhisho | King William's Town Province of the Eastern Cape South Africa

Wabsite: w.wv buffalocity.gov.za



BUFFALO CITY METROPOLITAN MUNICIPALITY

Directorate: Health, Public Salety & Emergency Services Office of the Chief Fire Officer P. O Box 673, East London, 5200 47 Fleet Street, East London 5201

Our ref.: Tel: 043 7059007 | Fax: 043 742 0092 Ifayile yethu: 17/10/1/3 Email: ZolekaM@buffalocity.gov.za Eng.; Mrs N. Nanto Ons Verw.: Imibuzo: Ext. 9007 Your ref.: Navrae: Ifayile yakho: 08 FEBRUARY 2018 U Verw.:

The Manager Buffalo City TVET College Mfaxa Street N.U. 1 MDANTSANE TOWNSHIP 5219

Dear Sir/Madam


SAFETY INSPECTION LETTER FOR JOHN MDANTSANE TOWNSHIP KNOX BOKWE CAMPUS.

The Buffalo City Metropolitan Municipality Fire and Rescue Services conducted a fire safety inspection at above mention campus on the 16^{th} – 17^{th} January 2018 and the following was discovered. FINDINGS:

- No emergency alarm system in place.
- No fire early warning device installed in the building.
- No sufficient running man signs and arrow to show the direction to be travelled by

AND THE FOLLOWING NEED TO BE DONE:

- Emergency alarm system that can be used to inform the occupants in the event of All fire extinguishers are required to be serviced yearly.
- Store room stack should be 1 metre from the roof.
- One metre clearance is required to all fire equipment.
- Exit signage is required for the central garden.
- All Flammable storages are required to have bund wall.
- The book store room is required to have three extinguishers with a signage All hydrants require servicing and a pressure test by your service



- All Computer Laboratories are required to have smoke detectors.
- All doors that is a component of an escape route from any room require a running
- All doors in an escape route at the ground level, leads directly to a street or public JKB Hall require two Fire Hose Reel with a signage.
- At Data Capture Section all obstructions must be removed in the route of emergency
- All signage must meet SANS 1186 Approved, photolumicent and must be screwed

If you have any further que	ries regarding
1100 9007	ries regarding the above, please contact Mrs N. Nanto on
T. THOMPSON CHIEF FIRE OFFICER	±0.962 tig
Employee Number:	DATE: 08 FEBRUARY 2018
Authority Number:	- Line



BUFFALOCITYMETROPO A very greating with your





Ref: N. Ogilvie,

<u></u>

Wrs S. Jane

FROM:

N. B Ogilvie

DATE:

SUBJECT: SAFETY STATUS REPORT

The classe is a martier is some of at the time of complete.	All No.	5. Clore esse cleak experiement adhered to.	The Provider to complete task:	Althural scrying completed awaiting order number to	2. Smoke detectors fitted and are operational.		requires nament and wiring.	ent and new slaw	
санриз	V lan not	equipment.	09/2021 A quota		 the task at	the sm	Requir	completed NYC	
compasit could possibly be the book store and	an not aware of a storeroom at the jkh	equipment.	A quotation request will be sent out in July 2024		received the relevant service providers can complete the task at hand.	of this siren and if it is required to be connected to the smoke detector system once this information.	Require relevant information pertaining to the wiring	Comment	

down in firmation is surrect at the time of completion of report.

l'égratule.	hond.	14. Two hose reck inclusive of signage according to fire vervice provide not necessary due to current hose is 3.	13. Ground level call signage adhered to.	12. Escape routes signage adhered to.	11. Computer labs smoke detectors fitted and operational	10. Awaiting cervice provider to issue service and pressure test.	Hock storage facility is compliant according to fire service provider Compliant according to fire	6. Hammebile storage requirements not yet adhered to and will be addressed at next health and setek	7. Exit signage adhered to.	6. One-motor de	
completed to produced dismage.	v recline the filtered these since 2020 mos				service 09/2021	V Pressure tests will be considered.	be in 2022	V Due to cut in 2022	aditere to stacking requirements.	will speak to the people in charge of the book	



29/04/21

Buffalo City Metropolitan Municipality East London | Bhisho | King William's Toyn Province of the Eastern Cape South Africa

Website: www.buffalocty.gov.za



METROPOLITAN MUNICIPALITY

Directorate: Health, Public Safety & Emergency Services Office of the Chief Fire Officer P. O Box 673, East London, 5200 47 Fleet Street, East London 5201

Tel: 043 7059007 | Fax: 043 742 0092 Email: ZolekaM@buffalocity.gov za

Our ref.:

Ifayile yethu: 17/10/1/3

Ons Verw .:

Enq.;

Navrae:

Mrs N. Nanto

lmibuzo: Ext. 9007

Your ref.: Ifayile yakho:

U Verw.:

08 FEBRUARY 2018

The Manager Buffalo City TVET College St Marks Road EAST LONDON 5200

Dear Sir/Madam

FIRE SAFETY INSPECTION LETTER FOR BUFFALO CITY TVET COLLEGE, ST MARKS

The Buffalo City Metropolitan Municipality Fire and Rescue Services conducted a fire safety inspection at above mentioned campus on the 22nd January 2018 and the following was

FINDINGS:

- No emergency alarm system in place.
- No fire early warning device installed in the building.
- No sufficient running man signs and arrow to direct the direction to be travelled by

AND THE FOLLOWING NEED TO BE DONE:

- Emergency alarm system that can be used to inform the occupants in the event of All fire extinguishers require servicing yearly.
- Store room stack should be 1 metre from the roof.
- One metre clearance is required to all fire equipment.
- A Fire Extinguisher is required for each office and a person must not travel m
- All Computer Laboratories require smoke detectors.
 - All doors that is a component of an escape route from any room require a running man signage with an arrow.

BUREALOUT METROPOLITANIA INIO

- All doors in an escape route at the ground level, leads directly to a street or public place or to any approved open space require exit signage.
- All obstructions must be removed in an emergency routes.
- Assembly points must be marked clearly.
- Bursary Office required two extinguishers with a signage.
- All vendors must have Environmental Health Certificate.
- All signage must meet SANS 1186 Approved, photolumicent and must be screwed into the wall.

If you have any further queries regarding the above, please contact Mrs N. Nanto on [043] 705 9007

T. THOMPSON
CHIEF FIRE OFFICER

Tr/mn

Employee Number:

Authority Number:





Bullala City Metropolitan Municipality East London | Bhisho | King William's Town Province of the Easiern Cape South Airea

Websile: www.buffelocity.gov.za



BUFFALO CITY METROPOLITAN MUNICIPALITY Directorate: Health, Public Safety & Emergency Services Office of the Chief Fire Officer P. O Box 673, East London, 5200 47 Fiee! Street, East London 5201

Tel: 043 7059007 | Fex: 048 742 0082

Email: ZolekaM@buffalocity.gov.za Our ref.: Eno.: Mrs N. Nanto Ifayije yethu: 17/10/1/3 Your ref .: Imibuzo: Ext. 9007 Ons Verw.: Ifayile yakho: Navrae: U Verw.: 08 FEBRUARY 2018

The Manager Buffalo City TVET College Kings Street Campus EAST LONDON 5200

Dear Sir/Madam

FIRE SAFETY INSPECTION LETTER FOR KINGS STREET CAMPUS, BUFFALO CITY

The Buffalo City Metropolitan Municipality Fire and Rescue Services conducted a fire safety inspection at the above mentioned campus on the 2nd February 2018 and the following was discovered. FINDINGS:

- > No emergency alarm system in place.
- No fire early warning device installed in the building.
- No sufficient running man signs and arrow to show the direction to be travelled by

AND THE FOLLOWING NEED TO BE DONE:

- Emergency alarm system can be used to inform the occupants in the event of any All fire extinguisher required to be service yearly.
- One metre clearance is required to all fire equipment.
- > A Fire Extinguisher is required for each office and the person must not travel more than 6 metres long to reach the fire equipment.
- > All passages must have smoke detectors.
- > Evacuation plan is required.
- Staircase signage is required.
 - All doors that is a component of an escape route from any room required

BUFFALOCITYMETROPOLITANMUNICIPALITY

they year was with your

- All doors in an escape route at the ground level, leads directly to a street or public place or to any approved open space require exit signage.
- All obstructions must be removed in an emergency route.
- Assembly points must be clearly marked.
- All signage must meet SANS 1186 Approved, photolumicent and screwed into the wall.

If you have any further queries regarding the above, please contact Mrs N. Nanto on [043] 705 9007

T. THOMPSON

CHIEF FIRE OFFICER

DATE: 08 FEBRUARY 2018

Employee Number:
Authority Number:



